

# UNSAFE GRINDING/CUTTING DISKS

It was brought to my attention yesterday afternoon by my safety officer that the fitters had complained about the cutting discs used with the mini grinders. They claimed that when they tried to use some of the new stock, that these discs were wobbling and skipping when they tried to cut steel.

I measured the new disc and found that the measurement from the central boss to the outer diameter varied by 1.5mm from one side to the other.

I have informed our material coordinators to check the stock that they have there, but if this is a common fault with them, I suggest we warn all of our departments who may have purchased these discs

